

The following Notice to Mariners is published for general information

Australia – Victoria

No. – 111 (T) - 2022

PORT MELBOURNE CHANGE OF MAINTAINED DEPTHS STATION PIER INNER AND OUTER EAST AND INNER WEST

Date: 29 March 2022

Refers: NtM 295 (T) / 2021 and is hereby cancelled.

Details: Mariners are advised that a change in maintained depth has been identified in the berth pocket of the following berths.

Table 3(j) Berth information, berthing and unberthing

Berth		Maintained depth (m)	Ship's limits at berth (m)		Wharf height (m) above Chart Datum	General remarks
Name	Length (m)	Berth	Max. draught	Max. length		
Station Pier Inner East	220	10.0	9.4	195	3.4	Bass Strait ferry terminal
Station Pier Inner West	95	7.9	7.3	105 ⁹	3.4	Cruise ship terminal Berthing also subject to passenger capacity and security requirements ⁹ Vessels with LOA >105 m may be accommodated on request

Station Pier outer East	223	10.7	10.1	240 ⁸	3.4	Cruise ship terminal Berthing also subject to passenger capacity and security requirements ⁸ Vessels with LOA >240 m may be accommodated on request
--	-----	------	------	------------------	-----	--

Refer below Diagram

**Charts &
Publications
affected**

(ENC) AU5MEL01, Harbours Master Direction (Table 3(j) Berth information, berthing and unberthing

Further notice:

Further Notice will be issued.



**David Shennan
Harbour Master**