

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 26 August 2022**  
**Australia – Victoria**

**No. 285 – 2022**

**Local Port of Port Phillip**

**Queenscliff**  
**Boat Ramp Lateral Mark Buoys Installed**

**Date:** **Immediate**

**Details:** Mariners are advised that two lit lateral mark buoys have been installed in the vicinity of Queenscliff boat ramp, as outlined in the table below

Latitude	Longitude	Function	Light Characteristics
38° 15.767'S	144° 39.871'E	Port Lateral buoy	Fl.R.2s
38° 15.754'S	144° 39.835'E	Starboard Lateral buoy	Fl.G.2s

Shallow water exists outside of this channel, particularly towards the bank on the eastern side of the facility adjacent to the bridge.

**Mariners are advised to keep within the channel and navigate with caution within the vicinity of Queenscliff Boat Ramp.**

**Charts & Publications**

**Affected:** AUS 143, 144, 158

**Further Notice:** No further Notice will be issued.

**If you require any further information, please contact the Borough of Queenscliffe on (03) 5258 1377.**

David Ritman

Manager Regional Planning  
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).