

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 29 August 2022**  
**Australia – Victoria**

**No. 288 – 2022**

**Local Port of Port Phillip**

**Sandringham**  
**Sandringham Harbour – Starboard Lateral Buoy Reinstated**

**Date:** Immediate

**Previous Notices:** 274(T) – 2022 is referred and cancelled.

**Details:** Mariners are advised that the Lit Starboard Lateral Buoy with characteristics FI(2)G.5s, situated 30m from the end of Sandringham Breakwater at approximate location 37°56.507'S, 144°59.532'E (WGS84) has been reinstated.

**Charts & Publications**

**Affected:** AUS 143, 155

**Further Notice:** No further Notice will be issued.

**If you require any further information please contact Parks Victoria on 13 1963.**

David Ritman

Manager Regional Planning  
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).