

VICTORIAN NOTICE TO MARINERS

The following Notice to Mariners is published for general information.

Victorian NTM 330 - Buoy 24 and Buoy 33 temporarily unlit

Effective 30th September 2022

Details: Buoys listed below are temporarily unlit

Buoy 24 in position 38° 21.5772′ S
Buoy 33 in position 38° 17.7774′ S
145° 14.1547′ E
145° 13.8739′ E

Mariners are advised to proceed with extreme caution when in the vicinity of these buoys

Further Notice: A further notice will be issued

Capt. Shane Vedamuttu

Harbour Master

Port of Hastings