

The following Notice to Mariners is published for general
information.

Victorian NTM 379 - Buoy 24 temporarily unlit

Effective 28th October 2022

Details: Buoy 24 in position 38° 21.5772' S 145° 14.1547' E
temporarily unlit

Mariners are advised to proceed with extreme caution when in
the vicinity of this buoy

Further Notice: A further notice will be issued



Capt. Shane Vedamuttu

Harbour Master

Port of Hastings