

Australia – Victoria
No. 431 (T) - 2022
PORT OF MELBOURNE
SOUTH WHARF 26
REDUCTION IN MAINTAINED DEPTH

Date: 1 December 2022

Refers: N/A

Details: Mariners are advised that a reduction in maintained depth has been declared in the berth pocket of South Wharf 26.

3.15 Berth information, berthing and unberthing - Table 3(j) – Harbour Master's

Directions – Melbourne Edition 13 – amended as follows:

Berth		Maintained depth (m)	Ship's limits at berth (m)		Wharf height (m) above Chart Datum	General remarks
Name	Length (m)	Berth	Max. draught	Max. length		
South Wharf 26	266	10.7	10.1	215	3.5	Bulk cement berth

For more information, contact Melbourne VTS on (03) 9644 9700 or on VHF Channel 12.

Charts & Publications affected Harbour Master's Directions - Melbourne Edition 13, September 2022
ENC AU5MEL01

**Further
notice:**

Further notice will be issued.



**Warwick Laing
Harbour Master**

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au