

Victorian Notice to Mariners

The following Notice to Mariners is published for general information

Australia – Victoria

No. – 436 (T) - 2022

PORT MELBOURNE PORT PHILLIP TEMPORARY WAVE MONITORING BUOYS ESTABLISHED AT PORT MELBOURNE WATERS AND LOCAL PORT OF PORT PHILLIP-EXTENDED

Date: 02 December 2022

Refers: NtM 419 (T) / 2021 and is hereby cancelled.

Details: Mariners are advised that the buoys established in the following positions, within the local Port of Port Phillip & Port of Melbourne waters, will remain in place until on or about November 2023.

Approximate Location	Latitude	Longitude	Characteristics
Port Melbourne Waters			
Werribee	37º 59.100´ S	144º 46.512' E	FL (Y) 2.5s
Centre of Bay	38º 03.804´ S	144º 52.002' E	FL (Y) 2.5s
Local Port of Port Phillip			
Sandringham	37º 58.719' S	144º 59.730' E	FL (Y) 2.5s
Mt Eliza	38° 09.731' S	145° 03.261' E	FL (Y) 2.5s
Rosebud	38° 18.087' S	144° 52.364' E	FL (Y) 2.5s

For further information contact Melbourne VTS on VHF Channel 12 or 9644 9700.

144° 45.184' E

FL (Y) 2.5s

Mariners are advised to navigate with caution in the vicinity of the Buoys

38° 08.156' S

Charts & Publications AUS 143,150, 155 and 158 affected

Indented Head

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.

Further Notice will be issued Further notice:

Warwick Laing Harbour Master



YELLOW MONITORING BUOY

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic) The requirements of section 232(2) have been taken into account.