

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 30 March 2023 Australia – Victoria

No. 145(T) – 2023

Local Port of Port Phillip

West Channel West Channel Beacon Remediation Works

Date: 3 April to 21 April 2023, weather permitting.

Details: Mariners are advised that Beacon remediation works, including underwater works, at the West Channel will be undertaken during the period in the locations as outlined in the table and shown in the sketch below from Beacon No:13 to Beacon No.2.

The installation works will require the use of the following Marine plant:

- Taylia-Rose Crew transfer
- DSV Matilda Mae Dive support vessel
- Dangerfield Work Vessel

Mariners are advised during marine operations, a temporary exclusion zone with no wake of 100 metres will be established around the beacon, authorised vessels of the operations excepted.

Latitude (WGS84)	Longitude (WGS84)	Charted Beacon #	Function	Light Characteristic
38°15.616'S	144°42.417'E	2	Port Lateral	FI(2) R.4s
38°15.969'S	144°42.632'E	3	Starboard Lateral	FI(2) G.5s
38°14.732'S	144°43.008'E	4	Port Lateral	FI(2) R. 4s
38°14.813'S	144°43.193'E	5	Starboard Lateral	FI(2) G.4s
38°13.922'S	144°43.466'E	6	Port Lateral	FI(4) R.12s
38°13.995'S	144°43.677'E	7	Starboard Lateral	FI(2) G.4s
38°13.042'S	144°43.970'E	8	Port Lateral	FI(2) R.4s



OFFICIAL// Publicly Accessible

Latitude (WGS84)	Longitude (WGS84)	Charted Beacon #	Function	Light Characteristic
38°13.034'S	144°44.402'E	9	Starboard Lateral	FI(2) G.3s
38°12.361'S	144°44.479'E	10	Port Lateral	FI(2) R.5s
38°12.369'S	144°44.993	11	Starboard Lateral	FI(2) G.5s
38°11.944'S	144°45.851'E	13	Starboard Lateral	FI(3) G.10s
38°15.728'S	144°41.473'E	Queenscliff Approach	Port Lateral	FI(2) R.3s
38°15.400'S	144°42.142'E	Swan Island Spit	Port Lateral	QR

Mariners are advised to navigate with minimum wash and exercise caution within the vicinity of the works.

Charts & Publications Affected: AUS 143, 155

Further Notice: A further Notice will be issued if any changes and on completion of works.

If you require any further information, please contact Parks Victoria on 13 1963.

Peter Kemp

A/Manager Regional Planning Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to <u>noticetomariners@parks.vic.gov.au</u>. To view Notices, visit <u>www.parks.vic.gov.au</u>



OFFICIAL// Publicly Accessible

OFFICIAL// Publicly Accessible

Asset ID: 1826 Plie name: Bea Coordinates: 38 11.944.% 144 45.851% Asset ID: 1624 Plie name: Bear Coordinates: 58 123615 144 66,479'E Asset D: 1525 Pile name: See Coordinates: 38 12.369'5 144 64.993'E Asset ID: 1822 Pile name: Sea Coordinates: 38 13.042'8 144 42.979'E Asset ID: 1623 Plie name: Bea Coordinates: 38 13.034'9 144 64.402'E Asset ID: 1620 Plis name: Bea Coordinates: 36 13.92215 144 43.45515 Asset ID: 1621 Pile name: Bea Coordinates: 38 13.995°8 144 42.677°8 Asset1D: 1518 Planame: Bea Coordinates: 38 14.7325 144 42.000°E Asset ID: 1819 Plie name: Bea Coordinates: 36 14.813'S 144 43.193'E Asset ID: 206 Pile name: Swan Island Spit Coordinates: 28 15.400'S 144 42.142'E PER Asset ID: P1617 Pile name: Baso Coordinates: 38 15.969'S 144 42.632'E Asset ID: 196 Pilo name: Qu Coordinates: 36 15.725°5 144 41.473°E Asset10: P2012 Pile name: Beac Coordinates: 38 15.61615 144 42.41715 Lateral Mark - Port m 2 - (fluckey) Lateral Mark - Starboard 1

Port Phillip Bay - Aerial View



OFFICIAL// Publicly Accessible