

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

Australia - Victoria

No. – 153 (T) - 2023

## **PORT OF MELBOURNE**

## PORT PHILLIP - SOUTH CHANNEL - SHOAL AREAS -

## TEMPORARY VIRTUAL AIDS TO NAVIGATION ESTABLISHED AND OPERATIONAL INSTRUCTION FOR SOUTH CHANNEL

Date: 6 April 2023

Refers: NtM 324 (T) - 2022 Port of Melbourne South Channel - Temporary Virtual Aid to

Navigation and Operational Instructions for South Channel is hereby cancelled.

**Details:** Mariners are advised that surveys in the South Channel have identified areas of

shoaling which are marked by virtual buoys in the following locations:

Identification Message	Lat	Long	Shoal depth
TB 3	38° 17.635'S	144° 41.144'E	15.2m
TB 4	38° 17.751'S	144° 41.652'E	15.2m
TB 5	38° 18.047'S	144° 43.255'E	15.3m
TB 6	38° 18.202'S	144° 44.377'E	15.4m
TB 7	38° 19.067'S	144° 48.633'E	15.0m
TB 8	38° 19.741'S	144° 54.077'E	14.9m
TB 11	38° 19.390'S	144° 50.145'E	15.3m

Vessels with a draught of 13.50m and greater are advised to refer to the Operational Instruction (OI) No. 01 / 2023 (attached) when navigating in the South Channel.

A copy of this NtM and OI can be downloaded from Ports Victoria's website.

Mariners on deep draught vessels are advised to navigate with caution in the vicinity of the virtual buoys.

For further information, please contact Melbourne VTS on VHF Channel 12 or 9644 9700.

Charts & Publications

AUS 143, AUS 144, AUS 158

affected (ENC Cell Number) – AU5RIP01, AU439144

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.

Further notice: Further notice will be issued.

Warwick Laing Harbour Master