

The following Notice to Mariners is published for general information.

Victorian NTM 241 - 23 Western Port

Fairway Buoy Light Restored


Effective 06th June 2023 .

Details: Mariners are advised that the light on the Western Channel Fairway Buoy in position S 38° 30.21'; E 145° 05.36' E has been restored.

Chart Affected: AUS 151.

Previous Notice: Victorian NTM 240 (T) - 23 refers and is hereby cancelled.

This Notice is self cancelling



Capt. Martin Leavold

Deputy Harbour Master

Port of Hastings