

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 08 June 2023 Australia – Victoria

No. 244(T) - 2023

Local Port of Port Phillip

West Channel

West Channel Beacon Remediation Works Extended

Date: 9 June to 7 July 2023, weather permitting.

Previous Notice: 145(T)-23 is referred, 181(T)-23 is referred, 211(T)-23 is referred.

Details: Mariners are advised that the beacon remediation works at the West Channel,

have been extended. The beacon remediations will include underwater works and are occurring at the locations outlined in the table and shown in the sketch below,

from Beacon No.13 to Beacon No.2.

The installation works will require the use of the following Marine plant:

• Taylia-Rose – Crew transfer

DSV Matilda Mae – Dive support vessel

Dangerfield – Work Vessel

Mariners are advised of a temporary public exclusion area of 100 metres with no wake, around each beacon when works are under way.

| Latitude (WGS84) | Longitude (WGS84) | Charted Beacon # | Function | Light Characteristic |
|---------------------|----------------------|---------------------|----------------------|-------------------------|
| 38°15.616'S | 144°42.417'E | 2 | Port Lateral | FI(2) R.4s |
| 38°15.969'S | 144°42.632'E | 3 | Starboard Lateral | FI(2) G.5s |
| 38°14.732'S | 144°43.008'E | 4 | Port Lateral | FI(2) R. 4s |
| 38°14.813'S | 144°43.193'E | 5 | Starboard Lateral | FI(2) G.4s |
| 38°13.922'S | 144°43.466'E | 6 | Port Lateral | FI(4) R.12s |
| 38°13.995'S | 144°43.677'E | 7 | Starboard Lateral | FI(2) G.4s |
| 38°13.042'S | 144°43.970'E | 8 | Port Lateral | FI(2) R.4s |



OFFICIAL// Publicly Accessible

| Latitude (WGS84) | Longitude (WGS84) | Charted Beacon # | Function | Light Characteristic |
|---------------------|----------------------|-------------------------|----------------------|-------------------------|
| 38°13.034'S | 144°44.402'E | 9 | Starboard Lateral | FI(2) G.3s |
| 38°12.361'S | 144°44.479'E | 10 | Port Lateral | FI(2) R.5s |
| 38°12.369'S | 144°44.993 | 11 | Starboard Lateral | FI(2) G.5s |
| 38°11.944'S | 144°45.851'E | 13 | Starboard Lateral | FI(3) G.10s |
| 38°15.728'S | 144°41.473'E | Queenscliff Approach | Port Lateral | FI(2) R.3s |
| 38°15.400'S | 144°42.142'E | Swan Island Spit | Port Lateral | QR |

Mariners are advised to navigate with minimum wash and exercise caution within the vicinity of the works.

Charts & Publications

Affected: AUS 143, 155

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman

Manager Regional Planning Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.



OFFICIAL// Publicly Accessible

Port Phillip Bay - West Channel Aerial View



