

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

16 January 2024
Australia – Victoria

No. 020(T) - 2024

Local Port of Port Phillip

Sandringham
Sandringham Yacht Club Special Mark Buoy 'SYC1' Missing

Date: **Immediate**

Details: Mariners are advised that the Sandringham Yacht Club lit Special Mark Buoy SYC1, with characteristics Fl(4).Y.10s at approximate location (WGS84) 37° 57.810'S, 144° 58.876'E is missing.

The buoy and light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the missing buoy.

Charts & Publications

Affected: AUS143, AUS155, AU5SAN01, AU438144.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Sandringham Yacht Club on (03) 9599 0999.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.