

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

30 April 2024
Australia – Victoria

No. 183 - 2024

Local Port of Port Phillip

Hampton
Sandringham Harbour – Temporary Special Buoys Permanently Discontinued

Date: Immediate

Previous Notice: 548-23 is referred.

Details: Mariners are advised the nine temporary special mark buoys demarcating the demolished Hampton pier exclusion zone have been removed, their former positions were as tabled (WGS84):

1. 37°56.663'S, 144°59.788'E	2. 37°56.645'S, 144°59.777'E	3. 37°56.638'S, 144°59.750'E
4. 37°56.627'S, 144°59.753'E	5. 37°56.612'S, 144°59.765'E	6. 37°56.608'S, 144°59.777'E
7. 37°56.613'S, 144°59.795'E	8. 37°56.633'S, 144°59.797'E	9. 37°56.648'S, 144°59.810'E

Mariners are advised to navigate with caution in the vicinity of the former pier footprint as shallow water and submerged obstructions may exist.

Charts & Publications

Affected: AUS 143, AUS 155, AU5SAN01, AU438144.

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.